

Part - 1

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

(To be filled by the Head of School/ Institute)

1. Name of School : GURU NANAK PUBLIC SCHOOL, MULLANPUR, LUDHIANA
2. Location : NEAR PSPCL, Kailpur Road, V.P.O.-Mullanpur Ldh.
3. Plot Area : 36421-7076 Sq. Mts.
4. Plinth Area : 15000 Sq. Mts.
5. Number of Storey : Double
6. Year of Construction of Building :
7. Supervision of the qualified Engineer :
The Following details may be given :
 - a) Name of the Engineer : Mr. Harbans Singh Sehon
 - b) Address of Engineer : 7-A Sargodha Colony, Pakhowal Rd. Ldh.
 - c) Set of Structural drawing used in the construction, if available: Attached Map of Building
 - d) Name of the Architect : Mr. Harbans Singh Sehon
8. Whether the building has been constructed for the purpose :
 - a) School : (YES / NO) Yes
 - b) Residential purpose and converted for use as a School : (YES / NO) No
9. Materials used for roofs:
 - a) R.C.C. Slabs (YES / NO) Yes
 - b) R.S. Joist & Battons (YES / NO) No
 - c) Wooden Joists & Battons (YES / NO) No
10. Materials used for walls:
 - a) Mud Mortar (YES / NO) No
 - b) Cement Mortar (YES / NO) Yes
 - c) Lime Mortar (YES / NO) Yes
11. Flooring
 - a) Conglomerate (YES / NO) No
 - b) Terrazo (YES / NO) Yes
 - c) Brick Paving (YES / NO) No
12. Detailed Drawing indicating of the rooms along with size and location of doors and windows:
(Attached)

Signature with Stamp of the seal
of the School / Institution) **Principal**
Guru Nanak Public School(10+2)
MULLANPUR(Ludhiana)

PART - II

(To be filled by the S.D.O. of Panchayati Raj Department)

I have visited the above mentioned school on dated 19/10/2020..... And have Visually inspected if from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood, or if there is settlement of walls / foundations or caves of roof etc. Immediate inspection of the undersigned by arranged to check the stability and safety of the building.

This building can be safety occupied for normal use up to 31/3/2021.....
(indicate year up to which it can be used)

ਸੰਖਿਆ 1-345-46 ਮਿਤੀ 19-10-2020

1) ਮੁੱਖ ਮੰਡਲ ਸਕੂਲ ਨਾਲ ਖਾਸ ਖਾਸ ਪਬਲਿਕ ਖਾਸ ਮੁੱਖ ਮੰਡਲ ਸਕੂਲ ਸਿੱਖ ਮੁੱਖ ਮੰਡਲ (ਮੁੱਖ ਮੰਡਲ) ਦੇ ਖਾਸ ਸਿੱਖ ਮੁੱਖ ਮੰਡਲ ਸਕੂਲ ਹੈ।

2) ਖਾਸ ਖਾਸ ਸਿੱਖ ਮੁੱਖ ਮੰਡਲ ਸਕੂਲ ਦੇ ਖਾਸ ਸਿੱਖ ਮੁੱਖ ਮੰਡਲ ਸਕੂਲ ਹੈ।

Bevan
 ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
 ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 3,
 ਲੁਧਿਆਣਾ

ਸਿੱਖ ਮੁੱਖ ਮੰਡਲ

Bevan
 ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ
 ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 3,
 ਲੁਧਿਆਣਾ